

Inspection Photos
Location Name: Centennial 32-33
API: 05-123-21239



Photo 1: Location, looking NE



Photo 2: Wellhead looking SW

Inspection Photos
Location Name: Centennial 32-33
API: 05-123-21239



Photo from prior inspection for comparison



Photo 3: Separator anchored

Inspection Photos
Location Name: Centennial 32-33
API: 05-123-21239



Photo from prior inspection for comparison



Photo 4: Concrete vault anchored. Berm is earthen in floodplain.

Inspection Photos
Location Name: Centennial 32-33
API: 05-123-21239



Photo from prior inspection for comparison



Photo 5: Riser removed.