

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #1 – View of pump jack and wellhead from SE corner.  
Note oil-stained soil beneath wellhead and shed.**



**Photo #2 – Oil-stained soil at wellhead and day tank lacking secondary containment at SE corner of pump jack. Note oily rag attached to polished rod/wellhead and damaged panel fence at shed.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #3 – Localized oil-stained soil beneath 1-gallon chemical storage container (which lacks secondary containment device) at SW corner of pump jack.**



**Photo #4 – 55-gallon drum on west side of pump jack is open to atmosphere and lacking secondary containment device. Drum contained unknown amount of fluid on date of inspection.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #5 – Localized, oil-stained soil beneath pump jack exhaust and north side of shed.**



**Photo #6 – Localized, oil-stained soil seeping from east side of shed.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #7 – Oil-saturated soil beneath prime mover (1).**



**Photo #8 - Oil-saturated soil beneath prime mover (2).**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #9 – Localized accumulation of oily waste beneath valve on east side of 400 bbl crude oil AST. Note proximity of production facility to inhabited buildings to NE.**



**Photo #10 – Historical accumulation of oily waste beneath valve on west side of crude oil AST.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #11 – Uncapped 2" flowline riser SW of crude oil AST.**



**Photo #12 – Bullplugged 2" riser south of crude oil AST.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #13 – Unused pipe at SE corner of crude oil AST.**



**Photo #14 - Shallow, eroded earthen berm NE of crude oil AST and proximity to occupied buildings NE of production facility.**

Inspection Photos  
Location Name: Hill 6-1  
API: 05-123-20169  
Inspection Date: October 17, 2017



Photo #15 – View of separator shed and propane tank from NW corner.



Photo #16 – Battery sign located at NE corner of separator shed fenceline.

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #17 - 55-gallon drum lacking secondary containment and damaged barbed wire fence on east side of separator shed. Note uncapped 2" pipe riser in foreground.**



**Photo #18 – Uncapped 2" pipe riser NE of separator shed contained crude oil.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #19 – Historical accumulation of oily waste beneath SE corner of separator shed.**



**Photo #20 – Oil-stained soil and historical accumulations of oily waste inside of separator shed (1).**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #21 - Oil-stained soil and historical accumulations of oily waste inside of separator shed (2).**



**Photo #22 – 110 bbl fiberglass PBV SW of separator shed.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #23 – Earthen berm for fiberglass produced water PBV is shallow at SE corner.**



**Photo #24 – Earthen berm for fiberglass produced water PBV is shallow south of tank.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #25 – Off-site sediment transport from pit berm onto area north of pit fence.**



**Photo #26 – Stockpile of oily waste remains west of skim tank.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #27 – Fiberglass skim tank lacks earthen berms on west, north, and east sides as well as volume label.**



**Photo #28 – Uncontrolled weeds growing inside of and around pit.**

**Inspection Photos**  
**Location Name: Hill 6-1**  
**API: 05-123-20169**  
**Inspection Date: October 17, 2017**



**Photo #29 – Oil-stained soil inside of pit (1), SE corner.**



**Photo #30 - Oil-stained soil inside of pit (2), NW corner.**