

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #1 – View of wellhead and pump jack from the northwest. Note that precipitation is pooling on well pad.



Photo #2 – Day tanks at south end of pump jack. 55-gallon drum/day tank lacks secondary containment device and exhibits historical accumulation of both impacted soil and wind-blown weeds underneath.



Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #3 – Localized accumulations of oil-stained soil and wind-blown weeds at wellhead. Note fresh crude oil stains on equipment.



Photo #4 – Recent lube oil stains on east side of pump jack.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #5 – Oil-stained soil and pooling fluid on west side of pump jack.



Photo #6 – Localized accumulations of oil-stained soil beneath prime mover.

Inspection Photos

Location Name: Hoffman 34-10

API: 05-123-20097

Inspection Date: October 17, 2017



Photo #7 – Localized accumulation of oil-stained soil and wind-blown weeds at SW corner of pump jack.



Photo #8 – Precipitation accumulation and ruts NW of pump jack.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #9 – Ruts and precipitation pooling SE of pump jack.



Photo #10 – Precipitation and ruts east of pump jack.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #11 – Battery sign and eroded berms at SE corner of crude oil ASTs.



Photo #12 – Crude oil ASTs.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #13 – Localized, oil-stained soil at crude oil AST loadout valve.



Photo #14 – Localized, oil-stained soil and 2" pipe riser beneath uncapped valve on west side of northern crude oil AST.

Inspection Photos

Location Name: Hoffman 34-10

API: 05-123-20097

Inspection Date: October 17, 2017



Photo #15 – Valve on west side of southern crude oil AST lacks bullplug.

Photo #16 – 2" steel flowline risers SE of crude oil ASTs. Note that berms in background are eroded and damaged.



Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #17 – Produced water AST and separator shed.



Photo #18 – Puddle of water at 300 bbl produced water AST loadout.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #19 – 110 bbl produced water fiberglass PBV.



Photo #20 – Localized accumulations of oil-stained soil inside of separator shed (1).

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #21 - Localized accumulations of oil-stained soil inside of separator shed (2).



Photo #22 – Open-top skim tank at SE corner of production facility. Note oily rag and small pile of oily waste. Tank lacks NFPA placard and volume/content labels.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #23 – 2” pipe riser north of produced water pit.



Photo #24 – Localized accumulations of oil-stained soil and weeds at SW corner of produced water pit #273442.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #25 - Localized accumulations of oil-stained soil and weeds at NE corner of produced water pit #273442.



Photo #26 – View into first produced water pit #273442 from NE corner.

Inspection Photos
Location Name: Hoffman 34-10
API: 05-123-20097
Inspection Date: October 17, 2017



Photo #27 – Uncontrolled weed growth in NW portion of L-shaped pit (#273443).



Photo #28 – Uncontrolled weed growth in southern portion of L-shaped pit (#273443).

