

Inspection Photos
Location Name: Furr F3 Pad follow up
Location ID: 335021



Photo 1. Tank and sand trap have been disconnected from well but not removed from site as stated in FIRR Doc#401438181 CA# 104930 and 104931



Photo 2. Signs on tank still have incorrect operator information.

Inspection Photos
Location Name: Furr F3 Pad follow up
Location ID: 335021



Photo 3. Hatch on tank was found open by FIU staff.



Photo 4. Tank contained sand AND produced water.