

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2017

Submitted Date:

10/24/2017

Document Number:

689400540

FIELD INSPECTION FORM

Loc ID 335021 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Laramie Energy,		cogccnotifications@laramie-energy.com	All Inspections
Ash, Margaret		margaret.ash@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286088	WELL	PR	11/23/2008	GW	045-12612	FURR 15-22B	PR
286724	WELL	PR	11/25/2008	GW	045-12743	FURR 15-22 D	PR
286725	WELL	PR	11/24/2008	GW	045-12742	FURR 10-22 D	PR

General Comment:

Follow up to inspection Doc#689400413 in response to FIRR Doc#401438181. Corrective actions have not been met. See the Signs and Markers, and the Tanks and Berms section of inspection.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Tank was still on location at time of inspection. Tank sign has another operators name and contact information on it. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/12/2017
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	800-891-6191	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Sand trap and tank have been disconnected from well but remain on location.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		
Comment:	Hatch was open on tank at time of inspection. Tank contained sand and produced water. All E&P waste that may be inside of the tank must be properly disposed of at an approved Facility. Provide any disposal manifests to NW Environmental Staff when tank is removed.				
Corrective Action:	Close gauge hatches when not accessing tank per Rule 605.a.(9). within 24 hours.				Date: 10/25/2017

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Tank is still on location. No containment around tank. Corrective action has not been met. See attached photo.			
Corrective Action:	Install berms or other secondary containment devices per Rule 906.d.(1).			Date: 11/13/2017

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 286088 Type: WELL API Number: 045-12612 Status: PR Insp. Status: PR

Facility ID: 286724 Type: WELL API Number: 045-12743 Status: PR Insp. Status: PR

Facility ID: 286725 Type: WELL API Number: 045-12742 Status: PR Insp. Status: PR

COGCC Comments

Comment	User	Date
<p>FIU staff arrived on location at 9:00am 10/24/17 after receiving FIRR Doc# 401438181 on 10/23/17 at 2:46pm. Under CA# 104930 for installing berms around tank, operator stated "This device is a sand trap not a tank, the item has been removed from the site." with a completion date of 10/23/17. The tank was still on location at the time of the follow up inspection. FIU staff was able to see and photograph through the open hatch on tank both sand and produced water at the time of the follow up inspection. Under CA# 104931 on FIRR Doc#401438181 operator stated "This is not a tank, therefore signGE NOT REQUIRED. Item has been removed from the location." with a completion date of 10/25/17. See attached photos of tank on location.</p>	conklinc	10/24/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400541	Photos from previous inspection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4282970
689400542	Furr F3 Pad follow up	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4282971