



Photo 1. View of the project area from the southwestern corner of the working area facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner of the working area facing eastward. Vegetation is well established on the southern fill slope, and largely comprised of western wheatgrass (*Pascopyrum smithii*), squirreltail (*Elymus elymoides*) and smooth brome (*Bromus inermis*).



Photo 3. View of the western portion of the project area from the southwestern corner of the working area facing northward. What appears to be a vegetated topsoil stockpile is present in the northwestern portion of the project disturbance.





Photo 4. View of wood debris and unused pipes in the southern portion of the project area. These need to be removed.



Photo 5. View of the eastern edge of the project area from the southeastern edge facing northward. Unused pipes and pump jack parts as well as small debris are present in this portion of the project area. These need to be removed.



Photo 6. View of unused chemical tank, pump jack parts, cement debris, and what appears to be oil stained soils in the northern portion of the project area. These need to be removed, and stained soils remediated or properly disposed of.



Photo 7. View of unused pipes stored in the northwestern portion of the project area. These need to be removed.