

## Inspection Photos



**Photo 1.** Facing northeast toward the location and main road that is used to access active well sites.



## Inspection Photos



**Photo 2.** Facing east toward the location.



## Inspection Photos



**Photo 3.** Facing east along the south fill slope.



## Inspection Photos



**Photo 4.** East side of the location facing west.



## Inspection Photos



**Photo 5.** There is plastic pipe at the southeast corner of the location.



## Inspection Photos



**Photo 6.** Facing southwest at the location.



## Inspection Photos



**Photo 7.** View of groundcover at the location. There was no gravel observed and vegetation appears to be establishing.



## Inspection Photos



**Photo 8.** North side of the location facing southwest.



## Inspection Photos



**Photo 9.** There is a pipe riser that remains at the east side of the location which appears to be marked for removal.



## Inspection Photos



**Photo 10.** Facing southeast at the location.