



Photo 1. View of the project area from the southeastern corner of the working area facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner of the working area facing southwestward. Revegetation is well established with grasses such as western wheatgrass (*Pascopyrum smithii*), and brome grass (*Bromus* sp.).





Photo 3. View of the eastern portion of the project area from the southeastern corner of the working area facing northward. Unused pipe needs to be removed and properly stored.



Photo 4. View of the western portion of the project area from the southwestern corner of the working area facing northward.



Photo 5. View of unused equipment stored in the southern portion of the project area.



Photo 6. View of more unused equipment and debris in the southern portion of the project area.



Photo 7. View of silt trap at culvert outlet along the access road.



Photo 8. View of sediment controls at culvert at the lease road.