



**Photo 1. View of the project area from the southern corner of the project area facing center. Frac tanks are stored on location.**



**Photo 2. View of the eastern portion of the project area from the southern corner facing northeastward. Revegetation in the outer portions of the project disturbance is well established with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), giant squirreltail (*Elymus multisetus*), and big sagebrush (*Artemisia tridentata*).**





**Photo 3. View of the southern portion of the project area from the southern corner facing northwestward.**



**Photo 4. View of musk thistles (*Carduus nutans*) that have flowered in the southern portion of the project area. Approximately 100 thistles were observed within the outer revegetation areas.**



**Photo 5. View of rock check dams along the access road that are full of sediment and need maintenance.**



**Photo 6. Another view of sediment filled rock check dams along the access road.**



**Photo 7. View of culvert along the access road that is in good condition.**