

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo 1: Location, looking N



Photo 2: Wellhead, looking W

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo from prior inspection for comparison



Photo 3: Stained soil worked

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo from prior inspection for comparison



Photo 4: Stained soil in engine house

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo from prior inspection for comparison



Photo 5: Unused pipe at wellhead

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo from prior inspection for comparison



Photo 6: Berms built up, tanks labeled

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo from prior inspection for comparison



Photo 7: Gap under netting

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo from prior inspection for comparison



Photo 8: Weeds in pit

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo 9: Unused equipment at manifold



Photo 10: Burrows in berms

Inspection Photos
Location Name: Hendershot #1
API: 05-123-05210



Photo 11: Stained soil at vessel



Photo 12: Wildlife egress