



Photo 1. View from the northwestern corner of the project area facing center. Pipe rack in the foreground does not appear to be in use.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation in the outer portions of the project disturbance is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and brome grass (*Bromus* sp.).



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4. View of the eastern cut-slope from the northeastern corner facing southward. This slope is not stabilized as evidenced by the exposed roots at the top of the slope, erosional rilling within the slope, and sediment deposition at the toe of the slope.



Photo 5. View of sediment deposition along the western edge of the access road, near the entrance to the access road facing northward.