

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2017

Submitted Date:

10/26/2017

Document Number:

681700929**FIELD INSPECTION FORM**Loc ID 435306 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435305	WELL	PR	09/17/2014	OW	123-38576	Wickstrom 6-4	EI

**General Comment:**[COGCC environmental inspection of well only. Refer to Field Inspection Report #681700927 for conditions at shared production facility.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Oily rag tied to wellhead. See photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/05/2017

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Localized, oil-stained soil at wellhead. See photos.			
Corrective Action:	Remove and properly dispose of oily waste, per Rule 907.e.			Date: 10/28/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Panel fence.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	Two 55-gallon drums inside of pump jack shed. See photos.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Day tank at SE corner of pumping unit lacks secondary containment device. See photos.		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).		Date: 11/26/2017
Type: Other	# 1		
Comment:	Oily rag tied to wellhead equipment. See photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 11/26/2017

<b>Venting:</b>			
Yes/No			

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 435305 Type: WELL API Number: 123-38576 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700949	Well sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285188">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285188</a>
681700950	Stained soil at wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285189">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285189</a>
681700951	Oily rag at wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285190">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285190</a>
681700952	Day tank lacking secondary containment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285191</a>
681700953	Chemical storage inside of shed.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285192">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285192</a>