

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2017

Submitted Date:

10/13/2017

Document Number:

688000086**FIELD INSPECTION FORM**Loc ID 313956 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
JAMES, STEVEN D	(303) 893-2438	steve@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256673	WELL	PR	10/15/2004	GW	087-08114	IMPALA RESOURCES AMBROSE 2-25	EI

**General Comment:**[Environmental inspection.](#)

Inspected Facilities									
Facility ID:	256673	Type:	WELL	API Number:	087-08114	Status:	PR	Insp. Status:	EI
Producing Well									
Comment:	Absorbent boom wrapped around wellhead below stuffing box. Slight oil stain on soil at wellhead.								
Corrective Action:	Continue absorbent boom use as needed. Clean up and properly dispose oil impacted soil. Provide photographs of clean soil at wellhead on a FIRR.							Date:	11/03/2017

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: 50Width: 30**Lining:**Liner Type: Liner Condition: Comment: Shallow pit north of the produced water tank.

Corrective Action

Submit an eForm 15 (Pit Report) documenting the pit.Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: 

Corrective Action

Date: **COGCC Comments**

Comment	User	Date
<u>Water disposal has periodically been reported as "P" pit production. Confirm the reporting and correct as necessary.</u>	youngr	10/13/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401436998	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4280686">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4280686</a>
688000087	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4280685">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4280685</a>