

Photo#1:
Overview of Location from Entry at SW corner.



October 24, 2017

Photo#2:

NE Corner of Location: Portions of Silt Fence are in disrepair. Note Russian thistle plants that have senesced, broken off and become Debris.



October 24, 2017

Photo#3:

North Fill slope area of Location : Portions of Silt Fence are in disrepair. Note Annual Weeds that have senesced , will break off , blow and become Debris.



October 24, 2017

Photo#4:

Another area where Silt Fence has become Debris



October 24, 2017

Photo#5:

Severe rutting / tracking and disturbance has occurred at SE corner of Location. Arrow indicates rutting leading out of Site to flagged area of future Pipeline / Road (?).



October 24, 2017

Photo#6:

View of Erosion along Secondary Access Road at NW corner of Location.



October 24, 2017

Photo#7:

Close up of Erosion along Secondary Access Road.



October 24, 2017