

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2017

Submitted Date:

10/29/2017

Document Number:

680102328**FIELD INSPECTION FORM**

Loc ID 447512	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 7 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>10598</u> Name of Operator: <u>SANDRIDGE EXPLORATION &amp; PRODUCTION LLC</u> Address: <u>123 ROBERT S KERR AVE</u> City: <u>OKLAHOMA CITY</u> State: <u>OK</u> Zip: <u>73102</u>																																																																																			
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>sandridgeenvironmental@sandridgeenergy.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment			sandridgeenvironmental@sandridgeenergy.com																																																																								
Contact Name	Phone	Email	Comment																																																																																
		sandridgeenvironmental@sandridgeenergy.com																																																																																	
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>447509</td><td>WELL</td><td>XX</td><td>08/29/2016</td><td></td><td>057-06576</td><td>Hebron 0780 7-18H</td><td>CI</td></tr> <tr><td>447510</td><td>WELL</td><td>XX</td><td>08/29/2016</td><td></td><td>057-06577</td><td>Hebron 0780 8-18H</td><td>CI</td></tr> <tr><td>447511</td><td>WELL</td><td>XX</td><td>08/29/2016</td><td></td><td>057-06578</td><td>Hebron 0780 10-18H</td><td>CI</td></tr> <tr><td>447513</td><td>WELL</td><td>XX</td><td>08/29/2016</td><td></td><td>057-06579</td><td>Hebron 0780 9-18H</td><td>CI</td></tr> <tr><td>447514</td><td>WELL</td><td>XX</td><td>08/29/2016</td><td></td><td>057-06580</td><td>Hebron 0780 6-18H</td><td>CI</td></tr> <tr><td>447586</td><td>WELL</td><td>XX</td><td>09/07/2016</td><td></td><td>057-06581</td><td>Coalmont 0781 1-13H</td><td>CI</td></tr> <tr><td>447587</td><td>WELL</td><td>XX</td><td>09/07/2016</td><td></td><td>057-06582</td><td>Coalmont 0781 2-13H</td><td>CI</td></tr> <tr><td>447589</td><td>WELL</td><td>XX</td><td>09/07/2016</td><td></td><td>057-06583</td><td>Coalmont 0781 4-13H</td><td>CI</td></tr> <tr><td>447590</td><td>WELL</td><td>XX</td><td>09/07/2016</td><td></td><td>057-06584</td><td>Coalmont 0781 5-13H</td><td>CI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	447509	WELL	XX	08/29/2016		057-06576	Hebron 0780 7-18H	CI	447510	WELL	XX	08/29/2016		057-06577	Hebron 0780 8-18H	CI	447511	WELL	XX	08/29/2016		057-06578	Hebron 0780 10-18H	CI	447513	WELL	XX	08/29/2016		057-06579	Hebron 0780 9-18H	CI	447514	WELL	XX	08/29/2016		057-06580	Hebron 0780 6-18H	CI	447586	WELL	XX	09/07/2016		057-06581	Coalmont 0781 1-13H	CI	447587	WELL	XX	09/07/2016		057-06582	Coalmont 0781 2-13H	CI	447589	WELL	XX	09/07/2016		057-06583	Coalmont 0781 4-13H	CI	447590	WELL	XX	09/07/2016		057-06584	Coalmont 0781 5-13H	CI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																												
447509	WELL	XX	08/29/2016		057-06576	Hebron 0780 7-18H	CI																																																																												
447510	WELL	XX	08/29/2016		057-06577	Hebron 0780 8-18H	CI																																																																												
447511	WELL	XX	08/29/2016		057-06578	Hebron 0780 10-18H	CI																																																																												
447513	WELL	XX	08/29/2016		057-06579	Hebron 0780 9-18H	CI																																																																												
447514	WELL	XX	08/29/2016		057-06580	Hebron 0780 6-18H	CI																																																																												
447586	WELL	XX	09/07/2016		057-06581	Coalmont 0781 1-13H	CI																																																																												
447587	WELL	XX	09/07/2016		057-06582	Coalmont 0781 2-13H	CI																																																																												
447589	WELL	XX	09/07/2016		057-06583	Coalmont 0781 4-13H	CI																																																																												
447590	WELL	XX	09/07/2016		057-06584	Coalmont 0781 5-13H	CI																																																																												

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447509	WELL	XX	08/29/2016		057-06576	Hebron 0780 7-18H	CI
447510	WELL	XX	08/29/2016		057-06577	Hebron 0780 8-18H	CI
447511	WELL	XX	08/29/2016		057-06578	Hebron 0780 10-18H	CI
447513	WELL	XX	08/29/2016		057-06579	Hebron 0780 9-18H	CI
447514	WELL	XX	08/29/2016		057-06580	Hebron 0780 6-18H	CI
447586	WELL	XX	09/07/2016		057-06581	Coalmont 0781 1-13H	CI
447587	WELL	XX	09/07/2016		057-06582	Coalmont 0781 2-13H	CI
447589	WELL	XX	09/07/2016		057-06583	Coalmont 0781 4-13H	CI
447590	WELL	XX	09/07/2016		057-06584	Coalmont 0781 5-13H	CI

**General Comment:**  
 This is a Construction and Stormwater Inspection. Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 10/17/17. Conditions at time of Inspection were Clear Sunny Skies, light breeze from the South at 60 degrees F. Elevation at Site is 8,196 ft.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

DEBRIS

Comment:

Populations of senesced annual weeds were noted, especially in North Fill slope area of Site. Non-Noxious weeds are considered debris if they have the potential to break off as annuals and blow around or off Location; they are considered debris when senesced /dead.

Corrective Action:

Remove the weeds (Debris) referenced above from location. Develop & implement weed control Plan for the Annual Non Noxious as well as Noxious Weeds in Spring of 2018

Date: 11/27/2017

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 447512

CDP: 

Comment:

It appears Location was initially Constructed in 2016; currently work is being conducted , basing, rocking of Pad Surface. No equipment was working at time of Inspection.

Corrective Action: Date: **Form 2A COAs:**

Comment:

Corrective Action: Date: **Wildlife BMPs:**

Comment:

Location is within SWH (Greater Sage Grouse).

Corrective Action: Date: **Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

	No		
Comments: Erosion BMPs:		Severe rutting / tracking and disturbance has occurred at SE corner of Location, where it appears heavy equipment has exited Location through wire gate. Deep rutting is also evident off location along flagged area which maybe identifying pipeline or road. Refer to photos attached.	
Other BMPs:			
Corrective Action:		Repair disturbed area, installing BMPs needed for perimeter controls. it should be determined who (Pipe line Co / Operator ?) caused rutting off Location and have disturbance addressed.	Date: 11/13/2017

  

	No		
Comments: Erosion BMPs:		Severe Erosion is occurring on fill slope side of what is identified in Drawings as Secondary Access Rd which runs along West side of site at North corner where road turns to East.	
Other BMPs:			
Corrective Action:		Repair road, installing BMPs to address erosion issues. Refer to Photos attached	Date: 11/27/2017

  

SILT FENCES	Yes		
Comments: Erosion BMPs:		Portions of Silt Fence are in disrepair and have become Debris. Refer to Photos attached.	
Other BMPs:			
Corrective Action:		Maintain /Repair Silt fence or remove if other BMP is installed as perimeter Control.	Date: 11/27/2017

  

**Comment:**

**Corrective Action:**  **Date:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name:  Address:

Phone Number:  Cell Phone:

Operator Rep. Contact Information:

Landman Name:  Phone Number:

Date Onsite Request Received:  Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name:  Phone Number:  Agreed to Attend:

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: <u>447509</u>	Type: <u>WELL</u>	API Number: <u>057-06576</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447510</u>	Type: <u>WELL</u>	API Number: <u>057-06577</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447511</u>	Type: <u>WELL</u>	API Number: <u>057-06578</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447513</u>	Type: <u>WELL</u>	API Number: <u>057-06579</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447514</u>	Type: <u>WELL</u>	API Number: <u>057-06580</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447586</u>	Type: <u>WELL</u>	API Number: <u>057-06581</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447587</u>	Type: <u>WELL</u>	API Number: <u>057-06582</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447589</u>	Type: <u>WELL</u>	API Number: <u>057-06583</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447590</u>	Type: <u>WELL</u>	API Number: <u>057-06584</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102330	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4286834">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4286834</a>