

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2017

Submitted Date:

10/23/2017

Document Number:

678301117

FIELD INSPECTION FORM

Loc ID 327274 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection
		zach.lisenfield@pdce.com	
		Karen.olson@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246626	WELL	PR	08/01/2017	GW	123-14423	SUCCO GAS UNIT 4-20	EI
442471	SPILL OR RELEASE	CL	07/08/2015		-	SPILL/RELEASE POINT	EI
452625	TANK BATTERY	AC	10/19/2017		-	Succo GU 4, 43-20 Battery	EI

General Comment:

[Complaint 200444285](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	See attached photo, inlet and outlet valves are closed and locked out. No spills of hydrocarbons observed at surface inside berm. All other valves on risers and piping in closed position as well. No hydrocarbon residue felt on outsides of any of the valves.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	#		
Comment:	no spills of hydrocarbons observed at surface area surrounding combustor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:	produced water vessel removed in 2015 subsequent to spill 442741 with initial 27 received as part of spill followup. Spill report requesting closure indicates data was provided documenting spill cleanup and PW tank removal. Data document is not found in COGCC records				
Corrective Action:	Provide documentation of PW vessel removal and soils analytical data to COGCC environmental staff (peter.gintautas@state.co.us) via email.				Date: 11/06/2017

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	no spill observed at surface inside containment berm surrounding crude tank.				
Corrective Action:			Date:		

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Adequate	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 246626 Type: WELL API Number: 123-14423 Status: PR Insp. Status: EI

Facility ID: 442471 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 452625 Type: TANK API Number: - Status: AC Insp. Status: EI

Complaint

Comment: [inspection done as part of investigation of complaint 200444285](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401437736	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281237
678301118	separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281230
678301119	wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281231
678301120	cruder tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281232