

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2017

Submitted Date:

10/23/2017

Document Number:

678301121**FIELD INSPECTION FORM**

Loc ID 333124 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 42640Name of Operator: HYNDREX RESOURCESAddress: 1531 4TH AVECity: GREELEY State: CO Zip: 80631-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Hyndrex		jamesberger2@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240925	WELL	SI	03/01/2017	OW	123-08713	NESSSU-KINDER 16	EI

General Comment:

battery not co-located with well and not inspected at this time.
inspection of Hyndrex facility near PDC facilities for complaint 200444285

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: no spills observed at surcae in area near pumpjack and wellhead.

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	pumpjack is disassembled but parts remain on site and is incapable of production as shown in attached photo		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240925 Type: WELL API Number: 123-08713 Status: SI Insp. Status: EI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: well is incapable of production as pump has been taken apart. See attached photoCorrective Action: Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3).
Contact COGCC engineering staff within 10 daysDate: 11/02/2017**COGCC Comments**

Comment	User	Date
<u>MIT required as well is temporarily abandoned status due to condition of pump</u>	gintautp	10/23/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401438105	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281581
678301122	pumpjack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281579