

Inspection Photos



Photo 1. 2013 aerial photo shows disturbance area of the access road and the location.

Inspection Photos



Photo 2. 2016 aerial photo shows disturbance area of the location.

Inspection Photos



Photo 2. Facing northwest toward the location which has not been recontoured and reclaimed.

Inspection Photos



Photo 4. Facing northwest at the location. There is undesirable weed growth (Kochia sp.) throughout the location.

Inspection Photos



Photo 5. Facing west at the location. The location is not recontoured and there are rows of soil piled up on the surface.

Inspection Photos



Photo 6. Facing southeast toward the cut slope.

Inspection Photos



Photo 7. Facing north along the west side of the location. There is a soil berm along this side of the location.