



Photo 1. View from the northern corner of the project area facing center.





Photo 2. View of the northern portion of the project area from the northern corner facing southwestward. Revegetation is progressing within the outer revegetation areas with western wheatgrass (*Pascopyrum smithii*) and sleepy grass (*Achnatherum robustum*).



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of area in the eastern portion of the project area with disturbed soil. Per onsite discussion with Gunnison Energy representative, area of disturbed soil in the eastern project area is from fill material brought in from road maintenance activities with the intention to reduce the slope of the eastern cut slope.



Photo 5. View of grass seedlings germinating in the eastern portion of the project area where there is recent soil disturbance.