

Inspection Photos
Location Name: UPRR 42 Pan Am N #3
API: 05-123-09102



Photo 1: Location, looking NE



Photo 2: Wellhead, looking SE

Inspection Photos
Location Name: UPRR 42 Pan Am N #3
API: 05-123-09102



Photo from prior inspection for comparison



Photo 3: Trash removed

Inspection Photos
Location Name: UPRR 42 Pan Am N #3
API: 05-123-09102



Photo from prior inspection for comparison



Photo 4: Produced water vault has no contents, capacities, safety labeling

Inspection Photos
Location Name: UPRR 42 Pan Am N #3
API: 05-123-09102



Photo from prior inspection for comparison



Photo 5: Decal replaced

Inspection Photos
Location Name: UPRR 42 Pan Am N #3
API: 05-123-09102



Photo from prior inspection for comparison



Photo 6: Bradenhead plumbed to surface.

Inspection Photos

Location Name: UPRR 42 Pan Am N #3

API: 05-123-09102



Photo from prior inspection for comparison



Photo 7: Battery sign corrected.



Inspection Photos
Location Name: UPRR 42 Pan Am N #3
API: 05-123-09102



Photo 8: Stained soil at oil tank



Photo 9: Stormwater erosion NW of battery