

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2017

Submitted Date:

10/30/2017

Document Number:

689400558**FIELD INSPECTION FORM**Loc ID 312444 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10144Name of Operator: XOG OPERATING LLCAddress: P O BOX 352City: MIDLAND State: TX Zip: 79702**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Crawford, Angie		acrawford@xogoperating.com	
Lujan, Carlos		carlos.lujan@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Engineering		dnr_cogccengineering@state.co.us	All Engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221619	WELL	SI	06/01/2012	GW	077-08221	ALSTATT 1	TA

General Comment:

Joint inspection with Reclamation Specialist Lou Colby and Environmental Specialist Carlos Lujan.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No sign at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/30/2017

Emergency Contact Number:

Comment:	No operator info or emergency contact on location.	Date: 11/30/2017
Corrective Action:	Install sign to comply with Rule 210.b.	

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:			corrective date
Type: Horizontal Heated Separator	# 0		
Comment:	Seperator has been removed from location.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 221619 Type: WELL API Number: 077-08221 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: All production equipment has been removed from location. Well last produced in April 2001. Passed MIT on 8/24/16. Flowlines abandoned on 6/15/17. Form 4 Doc#401391255 for annual TA status in process.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400561	ALSTATT 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4287887