

## Inspection Photos



**Photo 1.** Facing southeast along the access road. There are signs of erosion occurring down the road.

## Inspection Photos



**Photo 2.** Facing back northwest along the access road. There is stormwater erosion occurring along the side of the road and no BMP's are installed.

## Inspection Photos



**Photo 3.** Facing east toward the location.

## Inspection Photos



**Photo 4.** Facing southeast toward the south side of the location. Wood straw mulch has been applied to bare soil areas.

## Inspection Photos



**Photo 5.** Facing east toward the south side of the location. Wood straw mulch has been applied to bare soil areas.

## Inspection Photos



**Photo 6.** Facing west toward the location.

## Inspection Photos



**Photo 7.** There is still some plastic debris along the southeast cut slope.

## Inspection Photos



**Photo 8.** East side of the location facing northwest.