

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2017

Submitted Date:

10/31/2017

Document Number:

680102336**FIELD INSPECTION FORM**Loc ID: 451937 Inspector Name: Colby, Lou On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451937	LOCATION	AC	08/30/2017		-	Shiras CTB S11	CI

General Comment:

This is a Construction and Stormwater inspection, a Follow Up to Insp Doc#680102272 Dated 10/4/17. Form 42 (Notice of Construction) was Filed for this Location with start Date of 9/25/17 Conditions at time of Inspection were 64 degrees F and Sunny. Elevation at Site is 8,154 ft.

Location ConstructionLocation ID: 451937 CDP: _____

Comment: Location has dried out since previous Inspection. Trucks were laying Pit Run on top of liner on Pad Surface at time of Inspection. it appears Corrective Actions from previous Inspection have been resolved.

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:Comment: Location is in SWH; Greater Sage Grouse.

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS	Yes		

Comments: Erosion BMPs: Compromised Berm at SE corner of Site has been repaired.

Other BMPs: _____

Corrective Action: _____ Date: _____

WADDLES

Yes

Comments: Erosion BMPs: Wattles have been installed as Location perimeter controls. Many areas of Wattles do not appear to be properly installed per Good Engineering Practices. Refer to Photos attached.

Other BMPs:

Corrective Action: Install or repair required BMPs per Rule 1002.f.Date: 11/30/2017

Yes

Comments: Erosion BMPs: Culverts have been installed along Access Road.

Other BMPs:

Corrective Action: _____ Date: _____

Comment:Corrective Action:Date:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 451937 Type: LOCATION API Number: - Status: AC Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102341	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289189