

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2017

Submitted Date:

10/25/2017

Document Number:

674104358**FIELD INSPECTION FORM**
 Loc ID 319733 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone        | Email                     | Comment                         |
|--------------|--------------|---------------------------|---------------------------------|
| LLOYD, BILL  | 303-500-1170 | blloyd@petrosharecorp.com | <a href="#">ALL INSPECTIONS</a> |
| Behrens, Vic | 303-810-6382 | behrens@netecin.net       | <a href="#">Inspections</a>     |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 201168      | WELL | PR     | 05/11/2010  | GW         | 001-06571 | HABEL 'A' 1   | PR          |

**General Comment:**

**Location**

|                    |      |       |  |
|--------------------|------|-------|--|
| <b>Lease Road:</b> |      |       |  |
| Type               | Main |       |  |
| comment:           |      |       |  |
| Corrective Action  | L    | Date: |  |

Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: [ok](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                    |   |           |  |                                  |
|--------------------|---|-----------|--|----------------------------------|
| <b>Spills:</b>     |   |           |  |                                  |
| Type               | Area  | Volume    |  |                                  |
| Lube Oil           | Pump Jack   | >= 5 bbls |  |                                  |
| Comment:           | <a href="#">CLEAN UP STAINED SOIL</a>   |           |  |                                  |
| Corrective Action: | <a href="#">Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.</a> |           |  | Date: <a href="#">12/25/2017</a> |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                  |       |  |
|--------------------|----------------------------------|-------|--|
| <b>Fencing/:</b>   |                                  |       |  |
| Type               | PUMP JACK                        |       |  |
| Comment:           | <a href="#">ANGLE IRON FENCE</a> |       |  |
| Corrective Action: |                                  | Date: |  |

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| <b>Equipment:</b>  |     |       | corrective date |
| Type: Pump Jack    | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 201168 Type: WELL API Number: 001-06571 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: OK

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| DOCUMENT # 685503189, DATED 6/28/17 TRASH PICKED UP INSIDE SEPERATOR HOUSE, CLEANED UP STAINED SOIL INSIDE SEPERATOR HOUSE AND AROUND TANKS, BRADENHEAD PLUMBED TO SURFACE | montoyaj | 10/25/2017 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                       | URL   |
|--------------|-----------------------------------|---|
| 401441329    | INSPECTION SUBMITTED              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284194">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284194</a> |
| 674104360    | WELL SIGN AND SOILED DIRT         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284187">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284187</a> |
| 674104362    | BATTERY SIGN AND CONTROLLED WEEDS | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284188">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284188</a> |