

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2017

Submitted Date:

10/26/2017

Document Number:

681700928**FIELD INSPECTION FORM**Loc ID 418908 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418910	WELL	PR	05/13/2011	OW	123-32065	WICKSTROM 6-12	EI

General Comment:

[COGCC environmental inspection of wellhead only. Refer to Field Inspection Report #681700927 for conditions at shared production facility.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located at NE end of horizontal separator. Operator information is beginning to flake off. See photos.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Horizontal separator has uncapped 1" flowline leading to riser on west side of wellhead.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/26/2017
Type	WEEDS		
Comment:	Wind-blown weeds accumulating beneath horizontal separator. See photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/05/2017

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	NOT IN USE: Uncapped 1" flowline daylights from south end of horizontal separator to wellhead. See photos.		
Corrective Action:	Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan.	Date:	11/05/2017
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 418910 Type: WELL API Number: 123-32065 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401442327	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285194
681700944	Well sign at unused horizontal separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285183
681700945	Wellhead with plunger lift.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285184
681700946	1" flowlines on west side of wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285185
681700947	Weeds.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285186
681700948	Wellhead from south.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285187