

Inspection Photos  
Location Name: Aries 34-12  
API: 05-081-07088



**Photo 1. Excavation of flowlines.**



**Photo 2. Excavation of flowlines.**

Inspection Photos  
Location Name: Aries 34-12  
API: 05-081-07088



**Photo 3. Surface of cement plug.**



**Photo 4. Surface of cement plugs.**



Inspection Photos  
Location Name: Aries 34-12  
API: 05-081-07088



**Photo 5. Surface of cement plugs.**



**Photo 6. Backfilled area over abandoned flowlines.**

Inspection Photos  
Location Name: Aries 34-12  
API: 05-081-07088



**Photo 7. Overview of location taken from southwest corner facing northeast.**



**Photo 8. Overview of location taken at entrance facing west.**