

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2017

Submitted Date:

11/02/2017

Document Number:

682502765**FIELD INSPECTION FORM**
 Loc ID 317281 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 24320Name of Operator: DIAMOND OPERATING, INC.Address: 6666 GUNPARK DR STE #200City: BOULDER State: CO Zip: 80301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		davep@flatironenergy.com	

General Comment:

This is an inspection in regards to produced water discharge from the Marick State Tank Battery. On 11/1/2017, inspector observed produced water was being discharged from the over-flow siphon on the southeastern side of the tank, and from the manifold on the north end of the produced water tank into the containment berm. At 12:08 inspector called the emergency line on the sign and notified Mr. Tibson of the spill, that it needed to be stopped immediately, and to provide a 48 hour notice to perform clean-up. At approximately 13:30 inspector was contacted by Mr. Peterson with Diamond Operating. Inspector provided Mr. Peterson details of the spill and that a form 19 will need to be submitted. At approximately 14:00 inspector met with pumper on the site. Pumper was able to shut-in the wells and stop any additional discharge from occurring. The pumper informed inspector that they intended to remove the fluids and that a vacu-pump truck was on it's way.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: [Emergency contact number in working order.](#)

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	Tank	>= 5 bbls		
Comment: See summary comment and attached photos.				
Corrective Action: Perform clean-up, remove fluids discharged from the produced water tank and properly dispose in accordance with Rule 907.d.(2).				Date: <u>11/03/2017</u>

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Earthen berm around tank battery in proper functioning condition. Maintenance may be required post-cleanup.				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: [See summary comment and attached photos](#)Corrective Action: [Contact environmental and provide form 19.](#)

Date: 11/08/2017

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Note to operator: COGCC appreciates the prompt response from Diamond Operating Inc.	trujilloam	11/02/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682502767	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291891