



Photo 1. View from the northeastern corner of the project area facing center.





Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation in the outer portions of the project disturbance is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and brome grass (*Bromus* sp.).



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.





Photo 4. View of area in the northeastern portion of the working area, where tamarisk was observed in 2016 inspection. It does not appear to be present at this time.



Photo 5. View of the western portion of the project area from the southwestern corner facing northward. Stormwater diversions appear to be functioning at this time.