



**Photo 1. View of the project area from the western corner of the working area facing center.**





**Photo 2. View of the northwestern portion of the project area from the western corner facing northeastward.**





**Photo 3. View of the southern portion of the project area from the western corner of the working area facing southeastwestward. Vegetation is becoming established within the outer reclamation areas, and largely comprised of western wheatgrass (*Pascopyrum smithii*), big sagebrush (*Artemisia tridentata*) and big squirreltail (*Elymus multisetus*).**







**Photo 4. View of stormwater controls in the southern portion of the project area that appear to be functioning.**





**Photo 5. View of junk on the well pad.**





**Photo 6. View of unknown junk near the well pad entrance.**





**Photo 7. View of erosion occurring where stormwater runoff along the access road is eroding at the well pad entrance.**