

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2017

Submitted Date:

11/02/2017

Document Number:

689400568**FIELD INSPECTION FORM**Loc ID 324480 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|-----------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Ash, Margaret | | margaret.ash@state.co.us | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | NW Supervisor |
| SG Interests | | inspections@sginterests.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 283608 | WELL | PR | 08/01/2014 | GW | 051-06069 | FEDERAL 11-90-24 #1A | PR |

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. Copy of inspection will be sent to BLM.

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: (866) 261-9766

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Wire fence | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | panels | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|------------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 400 BBLS | HEATED STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 1 | 400 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | Date: | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

Venting:

| | | | |
|--------------------|-------|--|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

Flaring:

| | | | |
|--------------------|-------|--|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

| Inspected Facilities | | | | | | | | | |
|----------------------|---------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 283608 | Type: | WELL | API Number: | 051-06069 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Flowing | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Area of erosion near entrance of location with sediment migration down gradient. See attached photo.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 12/02/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 689400569 | Federal 11-90-24 #1A | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292278 |