

Inspection Photos
Location Name: URSA Operating LLC/Mclin B
API: 05-045-19375



Location



Wellheads with 2" pipe manifold connecting Bradenheads

Inspection Photos

Location Name: URSA Operating LLC/Mclin B

API: 05-045-19375



Gage on well B9



Gage on bradenhead manifold



Inspection Photos
Location Name: URSA Operating LLC/Mclin B
API: 05-045-19375



2" inlet pipe on right side of picture, coming from bradenhead manifold. Gas pass thru check valve then to gate valve into separator

