

Inspection Photos
Location Name: State #1 (13-36)
API: 05-123-09934



Photo 1: Location, looking NW



Photo 2: Wellhead, looking NW



Inspection Photos
Location Name: State #1 (13-36)
API: 05-123-09934



Photo from prior inspection for comparison



Photo 3: Stained soil at loadout

Inspection Photos
Location Name: State #1 (13-36)
API: 05-123-09934



Photo from prior inspection for comparison



Photo 4: Stained soil at engine

Inspection Photos
Location Name: State #1 (13-36)
API: 05-123-09934



Photo from prior inspection for comparison



Photo 5: Rutting in lease road

Inspection Photos
Location Name: State #1 (13-36)
API: 05-123-09934



Photo from prior inspection for comparison



Photo 6: Some lease road repairs

Inspection Photos
Location Name: State #1 (13-36)
API: 05-123-09934



Photo 7: Stormwater erosion on E side of location



Photo 8: Riser in tank battery