

Inspection Photos
Location Name: Smuggler #16-10-62
API: 05-123-31853



Photo 1: Location, looking SE



Photo 2: Wellhead, looking S

Inspection Photos
Location Name: Smuggler #16-10-62
API: 05-123-31853



Photo 3: No capacity on produced water decal

Photo 4: No capacity on crude oil decal

Inspection Photos
Location Name: Smuggler #16-10-62
API: 05-123-31853



Photo 5: Stained soil at loadout



Photo 6: Berms eroded low, some weeds in battery

Inspection Photos
Location Name: Smuggler #16-10-62
API: 05-123-31853



Photo 7: Stained soil at exhaust



Photo 8: Stained soil

Inspection Photos
Location Name: Smuggler #16-10-62
API: 05-123-31853



Photo 9: Stained soil in treater house



Photo 10: Debris in treater house

Inspection Photos
Location Name: Smuggler #16-10-62
API: 05-123-31853



Photo 11: Debris in treater house

