

Inspection Photos
Location Name: Dunbar #1
API: 05-123-23247



Photo 1: Location, looking SE



Photo 2: Wellhead, looking E

Inspection Photos
Location Name: Dunbar #1
API: 05-123-23247



Photo 3: Unused treater and treater house



Photo 4: Stormwater on SE corner of battery berm

Inspection Photos
Location Name: Dunbar #1
API: 05-123-23247



Photo 5: Stormwater erosion on SW corner of location



Photo 6: Stormwater erosion on W side of location

Inspection Photos
Location Name: Dunbar #1
API: 05-123-23247



Stormwater erosion on W side of location



Stormwater erosion on W side of location