



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused tank on site		
Corrective Action:	Comply with Rule 603.f .	Date:	02/05/2018

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	pipe		
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:	1 unmarked		
Corrective Action:	Mark all deadmen	Date:	11/20/2017
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Gas odor detected at meter run house. On-site personnel shut in wellhead and sales line		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216893 Type: WELL API Number: 069-06080 Status: PR Insp. Status: SI

**Complaint**

Comment: Complaint #: 200444595  
Field Inspector Assigned: C Pesicka  
Well Number: 05- Location #: 216893  
Inspection Document #: 684904677  
Nature of complaint: Odor  
If Sound GPS Coordinates of Survey Location: n/a  
Inspection Observations:  
An inspection of the above location was conducted with a focus on odor. Odor was detected around the meter house. Operator was contacted and the well was shut in at the wellhead and the sales line. On site personnel speculate that the leak may be in the flowline from wellhead to meter house. An integrity test of the flowline should be performed before the well can be put back into production.  
18A doc#: 200444600

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut in by personnel in response to odor at meter house

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684904678	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4294453">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4294453</a>