

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2017

Submitted Date:

10/30/2017

Document Number:

689400560**FIELD INSPECTION FORM**Loc ID 312502 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10144Name of Operator: XOG OPERATING LLCAddress: P O BOX 352City: MIDLAND State: TX Zip: 79702**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
Crawford, Angie		acrawford@xogoperating.com	
Colby, Lou		lou.colby@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Engineering		dnr_cogccengineering@state.co.us	All Engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221795	WELL	SI	06/01/2012	GW	077-08397	CHAFFIN 1	TA

General Comment:

Joint inspection with Reclamation Specialist Lou Colby and Environmental Specialist Carlos Lujan.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-888-683-3171

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Landowner has equipment stored on location.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221795 Type: WELL API Number: 077-08397 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Well last produced in April 2001. No production equipment on site. MIT on 8/25/16. Form 4 Doc#401391183 for continued TA status in process. Flowlines abandoned on 6/15/17.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater controls down gradient from well. Signs of erosion at edge of location in close proximity to live water.

Corrective Action: Install required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 11/30/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401445160	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4287893
689400563	CHAFFIN 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4287889