



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing within the revegetation areas with grasses and shrubs such as crested wheatgrass (*Agropyron cristatum*), dropseed (*Sporobolus* sp.), and rubber rabbitbrush (*Chrysothamnus nauseosus*). Surface owner is storing vehicles and equipment in the southern portion of the project area.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.





Photo 4. View of the eastern portion of the project area from the southeastern corner facing northward. Erosion is occurring within the western cut-slope. Stabilization is needed.