

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/25/2017
Submitted Date:
10/31/2017
Document Number:
680102336

FIELD INSPECTION FORM

Loc ID 451937 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:
6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451937	LOCATION	AC	08/30/2017		-	Shiras CTB S11	CI

General Comment:
This is a Construction and Stormwater inspection, a Follow Up to Insp Doc#680102272 Dated 10/4/17. Form 42 (Notice of Construction) was Filed for this Location with start Date of 9/25/17 Conditions at time of Inspection were 64 degrees F and Sunny. Elevation at Site is 8,154 ft.

Location Construction

Location ID: 451937 CDP: _____
Comment: Location has dried out since previous Inspection. Trucks were laying Pit Run on top of liner on Pad Surface at time of Inspection. it appears Corrective Actions from previous Inspection have been resolved.
Corrective Action: _____ Date: _____

Form 2A COAs:
Comment: _____
Corrective Action: _____ Date: _____

Wildlife BMPs:
Comment: Location is in SWH; Greater Sage Grouse.
Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS	Yes		

Comments: Erosion BMPs: Compromised Berm at SE corner of Site has been repaired.
Other BMPs: _____
Corrective Action: _____ Date: _____

WADDLES	Yes	
Comments: Erosion BMPs:	Wattles have been installed as Location perimeter controls. Many areas of Wattles do not appear to be properly installed per Good Engineering Practices. Refer to Photos attached.	
Other BMPs:		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date: 11/30/2017

	Yes	
Comments: Erosion BMPs:	Culverts have been installed along Access Road.	
Other BMPs:		
Corrective Action:		Date:

Comment:

Corrective Action: **Date:**

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 451937 Type: LOCATION API Number: - Status: AC Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401446060	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289195
401446229	Inspection Photos	Sandridge Shiras Loc#451937.pdf
680102341	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289189