

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2017

Submitted Date:

10/31/2017

Document Number:

680102337

**FIELD INSPECTION FORM**

Loc ID 451938 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451939	WELL	XX	08/30/2017		057-06602	Beaver Creek 0881 1-3H	CI

**General Comment:**

This is a Construction and Stormwater Inspection, a Follow Up to Isp Doc#680102273 Dated 10/4/17 Form 42 : NOTICE OF ONSTRUCTION: was Filed for this Site, Start Date 9/25/17. Conditions at time of Inspection were Sunny skies at 64 degrees F. Elevation at Site is 8,250 ft.  
Previous Inspection had 0# of Corrective Actions listed in Summary Findings Box; this was not Correct. Operator did respond to Corrective Actions in Construction Section of Inspection. It appears these CAs have been resolved.

**Location Construction**

Location ID: 451938 CDP: \_\_\_\_\_

Comment: Location has dried out since previous Inspection. It appears Corrective Actions from previous Inspection have been resolved. No Equipment was working at time of Inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: This Location is in a Sensitive Wildlife Habitat; Greater Sage Grouse.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

SLOPE ROUGHENING	Yes				
Comments: Erosion BMPs: <span style="color:blue;">BMPs have been installed at area of Concern at Access Road Corner turn in to Pad Entry.</span>					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action: _____				Date: _____	
BERMS	Yes				
Comments: Erosion BMPs: <input style="width:100%;" type="text"/>					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action: _____				Date: _____	
DITCHES	Yes				
Comments: Erosion BMPs: <input style="width:100%;" type="text"/>					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action: _____				Date: _____	
WADDLES	Yes				
Comments: Erosion BMPs: <span style="color:blue;">Wattles have been installed around Location as Perimeter Control. Many areas of Wattles do not appear to be properly installed per Good Engineering Practices.</span>					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action: <span style="color:red;">Install or repair required BMPs per Rule 1002.f.</span>				Date: <span style="color:red;">11/30/2017</span>	

**Comment:** Good effort has been made to implement CAs and stabilize site. Refer to Photos Attached.

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 451939 Type: WELL API Number: 057-06602 Status: XX Insp. Status: CI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401446552	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289769">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289769</a>
680102342	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289747">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289747</a>