

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2017

Submitted Date:

11/08/2017

Document Number:

688000094**FIELD INSPECTION FORM**

Loc ID 317126 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107602	PIT	AC			-	BARFKNECHT 1	EI
107603	PIT	AC			-	BARFKNECHT "P"	EI

General Comment:[Environmental inspection related to Rem #9049 Landfarm.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds on location and within the land treatment cell.		
Corrective Action:	Control weeds on the location and within the treatment cell.		Date: 11/30/2017
Type	TRASH		
Comment:	Pipe and tire in the southwest portion of the land treatment cell.		
Corrective Action:	Remove the pipe and tire and properly dispose.		Date: 11/30/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 107602	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
Facility ID: 107603	Type: PIT	API Number: -	Status: AC	Insp. Status: EI

Environmental**Spill/Remediation:**

Comment: [Oily soil on the western bank of the land treatment cell \(see photographs\).](#)

Corrective Action: [Ensure that oil or oily soil is not added to the treatment cell. Ensure that the entire cell is plowed, tilled or otherwise treated in order to enhance the biodegradation of petroleum hydrocarbons. Remove and properly dispose of the soil visibly impacted with oil as shown in the attached photographs.](#)

Date: 11/30/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000095	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4297802