

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2017

Submitted Date:

11/02/2017

Document Number:

682502765

**FIELD INSPECTION FORM**

Loc ID 317281 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 24320  
Name of Operator: DIAMOND OPERATING, INC.  
Address: 6666 GUNPARK DR STE #200  
City: BOULDER State: CO Zip: 80301

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		davep@flatironenergy.com	

**General Comment:**

This is an inspection in regards to produced water discharge from the Marick State Tank Battery. On 11/1/2017, inspector observed produced water was being discharged from the over-flow siphon on the southeastern side of the tank, and from the manifold on the north end of the produced water tank into the containment berm. At 12:08 inspector called the emergency line on the sign and notified Mr. Tibson of the spill, that it needed to be stopped immediately, and to provide a 48 hour notice to perform clean-up. At approximately 13:30 inspector was contacted by Mr. Peterson with Diamond Operating. Inspector provided Mr. Peterson details of the spill and that a form 19 will need to be submitted. At approximately 14:00 inspector met with pumper on the site. Pumper was able to shut-in the wells and stop any additional discharge from occurring. The pumper informed inspector that they intended to remove the fluids and that a vacu-pump truck was on it's way.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
Produced Water	Tank	>= 5 bbls		
Comment: <a href="#">See summary comment and attached photos.</a>				
Corrective Action: <span style="color: red;">Perform clean-up, remove fluids discharged from the produced water tank and properly dispose in accordance with Rule 907.d.(2).</span>				Date: <u>11/03/2017</u>

In Containment: Yes

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: <a href="#">Earthen berm around tank battery in proper functioning condition. Maintenance may be required post-cleanup.</a>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

**Venting:**

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date: <input type="text"/>	

**Flaring:**

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date: <input type="text"/>	

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action:  Date: 11/08/2017

Reportable: YES GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Note to operator: COGCC appreciates the prompt response from Diamond Operating Inc.	trujilloam	11/02/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401448324	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291893</a>
682502767	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291891">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291891</a>