

Inspection Photos



Photo 1. Facing north along the access road. There is vehicle rutting occurring along the road.

Inspection Photos



Photo 2. Facing northwest along the road. There is signs of vehicle rutting and widening of the road occurring.

Inspection Photos



Photo 3. Facing west toward the location.

Inspection Photos



Photo 4. There is a well sign installed however the operator name and emergency contact information is faded and not legible.

Inspection Photos



Photo 5. Facing toward the west side of the location. The vegetation has not established at this side of the location.

Inspection Photos



Photo 6. There is List B noxious weeds (Bull thistle) noticed at the location and along the access road.