

## Inspection Photos



**Photo 1.** Facing north along the access road. There is vehicle rutting and erosion occurring along the road.



## Inspection Photos



**Photo 2.** A diversion ditch was installed to divert stormwater off the road. This ditch has filled in with sediment and has created additional disturbance.



## Inspection Photos



**Photo 3.** The well sign is installed and legible.