

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2017

Submitted Date:

11/03/2017

Document Number:

680200101

**FIELD INSPECTION FORM**

Loc ID 427218 Inspector Name: KELLERBY, SHAUN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10515  
Name of Operator: GUNNISON ENERGY LLC  
Address: 1801 BROADWAY #1200  
City: DENVER State: CO Zip: 80202

**Findings:**

- 16 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Engineering		dnr_cogccengineering@state.co.us	All engineering
Leonard, Mike		mike.leonard@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
McWilliams, Dan		dan.mcwilliams@oxbow.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427223	WELL	PR	08/12/2013	GW	051-06103	DGU Hotchkiss Federal 1289 18-H1	PR
427241	WELL	PR	11/15/2012	GW	051-06104	DGU Hotchkiss Federal 1289 18-H2	PR
436613	WELL	WO	08/21/2014	LO	051-06124	DGU Federal 1289 18-CS2	WO
436614	WELL	DG	08/13/2014	LO	051-06125	DGU Federal 1289 18-CS1	WO

**General Comment:**

This is a routine field inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Any corrective action dates are based off of the date the inspection is submitted, not off of the inspection date

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	At Entry		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Excessive weed growth along the outer perimeter of location. Equipment stored or unused located on pad. Debris that appears to be pit liner is mixed into the soil along the north edge of this location.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/04/2017
Type	STORAGE OF SUPL		
Comment:	Equipment used during Drilling stored on location		
Corrective Action:	Comply with Rule 603.f .	Date:	12/04/2017
Type	OTHER		
Comment:	Flow line risers are not locked out on location.		
Corrective Action:	"Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."	Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	3 seperate well locations on this pad		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Generator and sub panel		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:	Separator unit is a 4 unit house that is in place but not hooked up or in use		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Transfer pump in housing		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	Some deadman are no longer marked as required.		
Corrective Action:		Date:	12/01/2017

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:	Date:	

<b>Inspected Facilities</b>			
Facility ID: <u>427223</u>	Type: <u>WELL</u>	API Number: <u>051-06103</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">Producing</span>	Corrective Action:		Date:
Facility ID: <u>427241</u>	Type: <u>WELL</u>	API Number: <u>051-06104</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">Producing</span>	Corrective Action:		Date:
Facility ID: <u>436613</u>	Type: <u>WELL</u>	API Number: <u>051-06124</u>	Status: <u>WO</u> Insp. Status: <u>WO</u>
<b>Idle Well</b>			
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____			
Comment: <span style="color: blue;">Well, has been drilled and is awaiting completion well was MIT document number 401138067.</span>	Corrective Action:		Date:
Facility ID: <u>436614</u>	Type: <u>WELL</u>	API Number: <u>051-06125</u>	Status: <u>DG</u> Insp. Status: <u>WO</u>
<b>Workover</b>			
Comment: <span style="color: blue;">No current MIT on record or delinquent as required by Rule 326</span>  <span style="color: blue;">Document number 401094509 was received August 16, 2016 providing ten-day notice of a mechanical integrity test on August 26, 2016. Field inspection document number 680401025 inspection date August 26, 2016 documents that it MIT, to maintain SI/TA status was completed with zero psi loss. COGCC database shows that a required Form 21 has not been submitted.</span>	Corrective Action: <span style="color: red;">Contact dnr_cogccengineering@state.co.us with resolution plan.</span>		Date: <u>11/17/2017</u>

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Check Dams	Pass					
				Covering Materials	Pass	
Gravel	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401449672	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293169">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293169</a>
680200102	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293161">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293161</a>