

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2017

Submitted Date:

11/06/2017

Document Number:

677400013**FIELD INSPECTION FORM**Loc ID 319168 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 39560Name of Operator: TOP OPERATING COMPANY FDBA MURRAY JAddress: 3609 S WADSWORTH BLVD STE 340City: LAKEWOOD State: CO Zip: 80235**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Deranleau, Greg		greg.deranleau@state.co.us	
Herring, Paul	303-727-9915	paul.herring@topoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243023	WELL	PR	08/10/2011	GW	123-10814	POWELL 1	PR

**General Comment:**

**Location****Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	ok		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD	>= 5 bbls		
Comment:	CLEAN UP SOILED DIRT			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 12/06/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	Plunger Lift	# 1		corrective date
Comment:	INTERMITTER CONTROLLER ON WELLHEAD			
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 243023 Type: WELL API Number: 123-10814 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Comment: OK

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
DOCUMENT # 681901529, DATED 10/11/16 WEEDS HAVE BEEN CONTROLLED NO HOUSE HOLD WITHIN 1000'OF THE WELL SITE THE WATER TANKS ARE BOTH TIED DOWN WITH CABLEW FOR FLOOD WATERS, PROD TANKS AND SEPERATERS NOT TIED DOWN WITH CABLES	montoyaj	11/06/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401451375	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295674">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295674</a>
677400015	WELL SIGN AND SOILED DIRT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295669">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295669</a>