

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2017

Submitted Date:

11/06/2017

Document Number:

680200091**FIELD INSPECTION FORM**
 Loc ID 324466 Inspector Name: KELLERBY, SHAUN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Inspections, All		inspections@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211720	WELL	PR	06/12/2012	GW	051-06042	JACOBS 29-1	PR

General Comment:

This is a routine field inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Any corrective action dates are based off of the date the inspection is submitted, not off of the inspection date.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: [Posted Emergency Contact Number 1-866-261-9766](#)

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds next to the well head and inside the fence around the tank battery.		
Corrective Action:	Comply with Rule 603.f .		Date: 11/10/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pig Station	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Transfer pump in shed			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	211720	Type:	WELL	API Number:	051-06042	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Chemical in containment
Other	Fail					No stabilization on cut slope
		Gravel	Fail			Gravel is space no longer effective as a BMP

Comment: Chemical is present in chemical containment at the well head. No cover is in place over containment, and is open to wildlife.

Corrective Action: Remove chemicals in containment and cover containment to prevent entry by wildlife.

Date: 11/10/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401450828	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295086
680200092	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295083