



Photo 1. View from the northern corner of the well pad facing center.





Photo 2. View of the northwestern portion of the well pad from the northern corner facing southwestward. Revegetation is progressing (although sparse on cut-slope) with grasses such as western wheatgrass (*Pascopyrum smithii*) and Indian ricegrass (*Achnatherum hymenoides*).





Photo 3. View of the northern portion of the project area from the northern corner facing eastward.



Photo 4. View of silt trap in the northeastern portion of the project area. Evidence of overflow and erosion downstream indicates silt trap needs maintenance.



Photo 5. View of area downstream of silt trap where sediment is being carried offsite and erosion is occurring.