

**Inspection Photos**  
**Location Name: Catamount Semler GU #1**  
**API: 05-067-07909**



**Secondary containment for lube oil container.**



**Stained soil and gravel near exhaust.**



**Inspection Photos**  
**Location Name: Catamount Semler GU #1**  
**API: 05-067-07909**



**Stained soil and gravel near muffler exhaust.**



**Location of spill/release #452581.**



**Inspection Photos**  
**Location Name: Catamount Semler GU #1**  
**API: 05-067-07909**



**Evidence of fluids in secondary containment berm.**



**Earthen dam near lateral extent of release.**