

Inspection Photos
Location Name: Catamount Herrera MV #1
API: 05-067-05410



Open topped produced water vessel with expanded metal cover.

Produced water vessel with insufficient capacity of secondary containment.

Inspection Photos
Location Name: Catamount Herrera MV #1
API: 05-067-05410



Secondary containment berm with insufficient capacity.



Animal burrow further compromising secondary containment berm.