

COGCC conducted an inspection of the Steve J 18-10 location (Location ID 333001) on October 26, 2017 (Document 689300334). During that inspection, COGCC made the following observations:

1. Storm Water: Location is washing out on east side of separator, discharging sediment off of location. Install or repair required BMPs per Rule 1002.f.

Response: Noble Energy repaired the erosion, tracked the slope, and installed rock at the drainage point.

Name: Steve J 18-10

Location ID: 333001

COGCC conducted an inspection of the Steve J 18-10 location (Location ID 333001) on October 26, 2017 (Document 689300334). During that inspection, COGCC made the following observations:

1. Storm Water: Location is washing out on east side of separator, discharging sediment off of location.

COGCC – 10/26/17



Photo 1. Location is washing out on east side of location, discharging sediment off of location.

Noble Energy – 11/6/17



Photo NBL1. Repaired areas of erosion and installed larger rock at the discharge point.

COGCC conducted an inspection of the Steve J 18-10 location (Location ID 333001) on October 26, 2017 (Document 689300334). During that inspection, COGCC made the following observations:

1. Storm Water: Location is washing out on east side of separator, discharging sediment off of location.

SPACE LEFT INTENTIONALLY BLANK

Noble Energy – 11/6/17



Photo NBL2. Repaired areas of erosion and tracked the slope of the pad.